



Technical Bulletin 137

Version 1.0

19th March 2013

Cub labelling

We have recently been made aware that the label on the Cub instrument has an incorrectly referenced IECEx Report number (IECEx BAS 11.003). The correct number should be IECEx BAS 11.0014. Please note, this only affects customers outside of the EU who have purchased a Cub instrument from us.

If you would like a replacement label showing the correct number you will need to return your Cub instrument to us and we will cover shipping costs. To return your instrument to us please contact our service department (details below) with the serial number(s) of the Cub unit(s) and we will send you a returns form with details of our courier account and instructions for the return at our cost.

By email: service@ionscience.com or martin.creasy@ionscience.com

By telephone: +44 (0)1763 208503

We would like to thank you for your co-operation in this matter.

Kind regards,

Alex Wadey-Leblond
Sales and Marketing Coordinator

