

Technical Bulletin 154

Version 1.1 24th July 2014

Update to CubPC software alarm levels

As part of our on-going commitment to provide you with the highest quality, our products are regularly tested to ensure they are operating at optimal levels and exceed customer expectations.

During some recent testing, we found that in some rare and specific circumstances the CubPC software may incorrectly select alarm levels. This only occurs when a gas is selected that has a particularly long name and is followed in the gas table by another gas with a near identical name.

We are pleased to inform you that this has been resolved and a new version of the CubPC software (V0.0.0.32) has been created to correct this error.

So no errors occur, we advise downloading the updated software from our website as soon as possible: [CubPC Software V0.0.0.32](#)

For further information please contact marketing@ionscience.com

T: +44 (0)1763 208503

W: www.ionscience.com

